

10 Maintenance Plan

Ryde Town Hall

March 2024



The Goddard Partnership Limited

Historic Buildings, Design and Conservation Consultants

The Old Fire Station Upper Basingwell Street Bishops Waltham Hampshire SO32 1PF

01489 890629

office@thegoddardpartnership.com

	Occasional and Regular Tas	sks																		
Ref	Building Element	Maintenance Task	Responsibility	Frequency	Rate £/Hour	Time	Frequency	Annual Cost	J	F	М	Α	М	J	J	Α	s	0	N	D
1.0	Roofs							2												
1.1.	Roofs areas generally (Flat Roofs)	Inspect roof areas from accessible high points and report any loss or damage.	Trained Staff*	i. After stormy weather	£30.00	1.5	12	£540.00	✓	√	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
1.2	Pitched lantern Lights	Check for broken glazing (pitched roofs and side panels)	Trained Staff*	Annually and after stormy weather	£30.00	1	4	£120.00	✓			✓			✓			✓		
		Check putty to glass	Trained Staff*	Annually	£30.00	2	1	£60.00										✓		
		Check lead flashings	Trained Staff*	Every six months	£30.00	5	2	£300.00				✓						✓		
1.3	Lead Flat roofs	Check covering and flashings remain secure (Lead theft)	Trained Staff*	Every six months	£30.00	1	2	£60.00				✓						✓		
		Check for splits	Trained Staff*	Annually	£30.00	1	1	£30.00										✓		
		Lead Parapet Gutters (Inspect for splits)	Trained Staff*	Annually	£30.00	1	1	£30.00										✓		
1.4	Single Ply Membrane Roofs	General review, examine for blisters/ splitting on joints	Trained Staff*	Annually	£30.00	1	1	£30.00										✓		
		Check lead flashings and flashings to SVP/ extracts	Trained Staff*	Every six months	£30.00	1.5	1	£45.00				✓						✓		
1.5	Asphalt Roofs	General review, examine for blisters/ splitting on joints	Trained Staff*	Annually	£30.00	1.5	1	£45.00				✓						✓		
		Check lead flashings	Trained Staff*	Annually	£30.00	0.5	1	£15.00										✓		
1.6	Pitched roofs	Check for missing slates (identification only, replacements by contractor)	Trained Staff*	Monthly between October and March	£30.00	1	1	£30.00	✓	✓	✓							√	✓	✓
		Check ridges (identification only, replacements by contractor)	Trained Staff*	Annually	£30.00	0.5	1	£15.00									√			
1.7	Lead weatherings and flashing	Make minor repairs (eg dress back clips, make good mortar fillets) (identification only)	Contractor	Annually				£600.00				✓								
1.8	Copings	Check aluminium cappings (identification only)	Trained Staff*		£30.00	1	1	£30.00												
1.9	Lightning Protection	Inspect and undertake testing by specialist	Contractor	Annually				£1,500.00				✓								
	Flagpole	Check fixings (identification only)	Contractor	Annually				£400.00												
1.11	Portico / Balcony Roof	Check mineral felt covering for splits (identification only)	Trained Staff*	Annually	£30.00	0.25	1	£7.50							√					
		Check lead flashings (identification only)	Trained Staff*	Annually	£30.00	0.25	1	£7.50							✓					
1.12	War Memorial Roof	Check for broken glazed panels (identification only)	Trained Staff*	Annually	£30.00	0.25	1	£7.50							✓					
2.0	Rainwater Disposal																			

	Occasional and Regular Tas	ks																		
Ref	Building Element	Maintenance Task	Responsibility	Frequency	Rate £/Hour	Time	Frequency	Annual Cost	J	F	М	Α	М	J	J	Α	s	0	N	D
2.1	Rainwater goods generally	Inspect rainwater goods from the ground and accessible high points and report any loss or damage (identification only)	Trained Staff*	i. During/after stormy weather ii. twice a year	£30.00	2	2	£120.00			√								√	
2.1.2		Clear rainwater goods of debris and ensure sumps and overflows are clear. Rod if necessary. Check that leaf guards are secure where they exist and that they are running freely	Contractor	Every three months			4	£2,000.00	✓			✓			✓			✓		
2.2	Rainwater Gutters	Check for missing sections of guttering (identification only)	Trained Staff*	Twice per year	£30.00	1	2	£60.00					✓						✓	
2.2.1		Check for leaks on joints between sections during heavy rain (identification only)		i. During/after stormy weather	£30.00	1	2	£60.00												
2.3	Rainwater Downpipes	Repair or replace any missing or cracked sections.	Contractor	Twice per year				£2,000.00					✓						✓	
2.4	Rainwater outlets/ hoppers from roof areas	Check to ensure all are running clear (during heavy rain) (identification only)	Trained Staff*	Twice per year	£30.00	1	2	£60.00					✓						✓	
2.5	Gulleys	Remove leaf debris. Inspect and keep gulleys clear.	Trained Staff*	Monthly	£30.00	2	12	£720.00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2.6	Below ground drainage	Open up inspection chambers. Check that all gullies and gratings are free twice per year from silt and debris and that water discharges freely.	Trained Staff*	Twice per year				£2,000.00					✓						√	
3	External Walls																			
3.1	External walls generally	Inspect external walls from the ground and accessible high points and report any damage, signs of movement (identification only)	Trained Staff*	i. After stormy weatherii. Annually	£30.00	5	2	£300.00			✓									
3.2	External walls	Remove any vegetation, ivy buddliea *	Contractor	Annually				£6,000.00					✓						✓	
3.2.1	Render	Check for signs of cracking/ loose render *	Contractor	Annually				With above					✓							
3.2.2	Rendered surrounds, pilaster strips, cornices etc	Check for signs of cracking/ loose render *	Contractor	Annually				With above					✓							
3.3.3	Ventilation	Ensure that ventilation grilles, air bricks, louvres etc are free from obstruction.	Trained Staff*	Twice per year	£30.00	1	2	£60.00			✓						✓			
3.4	Chimneys	Check pots and cappings. Remove vegetation	Contractor	Twice per year	£150.00	1	2	£300.00				✓					✓			
3.5	Stonework	Inspect stonework (identification only)	Trained Staff*	Annually	£30.00	2.5	2	£150.00			✓									
3.5.1		Inspect pointing (identification only)	Trained Staff*	Annually	£30.00	2.5	2	£150.00			✓									
3.6	Brickwork	Inspect stonework (identification only)	Trained Staff*	Annually	£30.00	2.5	2	£150.00			✓									
3.6.1		Inspect pointing (identification only)	Trained Staff*	Annually	£30.00	2.5	2	£150.00			✓									
3.7.1	Portico Columns	Check for signs of cracking/ loose render	Trained Staff*	Annually	£30.00	2.5	2	£150.00				✓								
								20.00												
4.0	Structural Movement	Tell-Tales to SE Corner	Monthly recording by staff. Interpretation by consultant	i) Monthly ii) Annual	£30.00	1	12	£360.00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
			Interpretation by consultant	ii) Annual				£300.00				√								
		Tell- Tales to West Pavilion	Monthly recording by staff.	i) Monthly	£30.00	1	12	£360.00	✓	✓	✓	✓	√	✓						
			Interpretation by consultant	ii) Annual				£300.00				✓								

	Occasional and Regular Tas	ks																		
Ref	Building Element	Maintenance Task	Responsibility	Frequency	Rate £/Hour	Time	Frequency	Annual Cost £	J	F	M	A	М	J	J	A	S	0	N	D
5	External Ironwork																			
5.1	Fire Escape stairs	Inspect for corrosion. Check for loose treads Check for slip resistance/ moss growth etc/ Powerwash	Consultant	Annually				£500.00			√									
5.2	Handrails to Portico Balcony	Inspect for corrosion	Trained Staff*	Annually	£30.00	0.5	1	£15.00			√									
5.3	Metal Railings	Inspect and undertake testing by specialist	Consultant	Annually							√									
5.4	Security Bars to windows	Inspect for corrosion	Trained Staff*	Annually	£30.00	0.5	1	£15.00			√									
6.0	Clock Tower																			
6.1	Structural Movement	Check and record tell-tales	Monthly recording by staff. Interpretation by consultant	i) Monthly ii) Annual	£30.00	1	12	2 £360.00	✓	√	✓	√	√	✓	✓	✓	✓	✓	✓	✓
			Interpretation by consultant	ii) Annual				£300.00				✓								
6.2	Render	Check for signs of cracking/ loose render (with *)	Consultant	ii) Annual				£1,200.00												
6.3	Glass to clock faces	Check glazed panels remain secure	Trained Staff*	Annually	£30.00	1	1	£30.00				√								
6.4	Roof																			
		Check Copper fish scales remain complete (visual inspection from roof level) (identification only)	Trained Staff*	Every six months	£30.00	0.5	2	£30.00	√						√					
		Check flat roof below cupola (identification only)	Contractor	Annually				£250.00	✓											
6.5	Other	Bellframe (identification only)	Contractor	Annually				£150.00	√											
		Terracotta Detailing (visual inspection from roof level)	Trained Staff*	Every six months	£30.00	0.5	2	£30.00	✓											
7.0	External Joinery																			
7.1	Main entrance doors	Check operation of hinges, bolts and locks (security) and report any problems.	Trained Staff*	Monthly	£30.00	1.5	1	£45.00												
7.2	Windows	Inspect windows and make essential minor repairs to glazing* or temporary covers.	contractor	Twice per year				£3,500.00				√							√	
7.3	Internal Doors	Check operation of hinges, closing etc.	Trained Staff*	Annually	£30.00	7.5	1	£225.00			√						√			
7.4	Windows	Inspect and clean	Contractor	Twice per year				£400.00				√							√	
7.5	Rooflights	Inspect																		
8	Internal Structure																			

Building Element	Maintenance Task	Responsibility	Frequency	Rate £/Hour	Time	Frequency	Annual Cost	J	F	М	Α	М	J	J	Α	s	0	N	D
Internal spaces generally	Inspect roof voids and internal spaces, particularly below parapet gutters and alongside downpipes. Report on any evidence of roof or gutter leaks.	Trained Staff*	i. During/after stormy weather. ii Annually	£30.00	7.5	1	£225.00			✓									
	Check for Unauthorised access (forced entry)	Trained Staff*	Fortnightly	£30.00	2	24	£1,440.00	✓	√	√	√	✓	√	√	✓	√	√	√	√
Basement	Check for leaks to oil tank	Trained Staff*	Every 3 months and before refilling	£30.00	0.5	4	£60.00	✓			✓			✓			✓		
Exposed woodwork	Inspect exposed woodwork and surfaces below for signs of woodworm infestation. Report any beetles or fresh wood dust (Frass)	Trained Staff*	Annually	£30.00	5	1	£150.00					√							
Roof and floor voids	Check roof and floor voids, inspect for signs of vermin and remove. Avoid using poison where bats are roosting.	Contractor	Every 4 months				£1,200.00									✓			
Lath and plaster ceilings	Inspect from mobile access platform	Staff/ Contractor	Annually				£1,200.00											✓	
Suspended Ceilings	Inspect from mobile access platform	Staff/ Contractor	Annually				With above											✓	
Stairs	Check handrails	Trained Staff*	Annually	£30.00	1.5	1	£45.00											✓	
Fire doors	Check slam action and closing	Trained Staff*	Monthly	£30.00	2.5	12	£900.00	✓	✓	✓	✓	✓	√	√	✓	√	✓	√	✓
Windows	Check window limiters remain in place. Review for rot	Trained Staff*	Every six months	£30.00	1.5	2	290.00	✓						✓					
Generally	Ventilate the building	Trained Staff*	Monthly on dry days	£30.00	1.5	2	290.00					√	✓	✓	✓	✓			
Building Services	(All once operational, Unless stated)																		
Heating system	Service heating system and update the service schedule.	Approved Code of Practice engineer	Annually				£3,000.00					✓							
Water	Ensure that all exposed tanks, water pipes and heating pipes are protected against frost. (Immediate)	Trained Staff*	During the winter months	£30.00	1.5	5	£225.00	✓	✓	✓								✓	✓
Fire fighting equipment	Service fire extinguishers	Specialist	Annually ** (with electrical test)				£1,500.00									✓			
Ladders/Fallarest	Check for correct operation/fixings. (Immediate)	Specialist	Annually				£1,200.00									✓			
Lighting	Replace lamps in light fittings (including access)	Contractor	Monthly	£200.00		12	£2,400.00	✓	√	✓	✓	✓	√	√	√	√	√	√	✓
Emergency Lighting	Test and service (Immediate) Key switch test ONLY	Trained Staff*	Twice per year				£750.00		✓							✓			
Fire detection	Test fire alarm system, including smoke and heat detectors. (Immediate)	Contractor	Annually ** (with electrical test)				£1,500.00				✓						✓		
Drainage	Rod the system (Immediate)	Contractor	Annually				£2,000.00									√			
Mechnical extracts	Check for correct operation/fixings.	Contractor	Annually ** (with electrical test)										√						
IT Wiring	Check for correct operation/fixings.	Contractor	Annually										√						
Lift	Test and service	Contractor	Annually				£1,500.00						√						
Clock	Servicing	Specialist	Annually				£600.00						√						
	Check clock weight	Specialist	With above				With above						√						
Organ Blower	Servicing	Specialist	Annually				£700.00						√						
	Internal spaces generally Basement Exposed woodwork Roof and floor voids Lath and plaster ceilings Suspended Ceilings Stairs Fire doors Windows Generally Building Services Heating system Water Fire fighting equipment Ladders/Fallarest Lighting Emergency Lighting Fire detection Drainage Mechnical extracts IT Wiring Lift Clock	Internal spaces generally below parapet gutters and alongside downpipes. Report on any evidence of roof or gutter leaks. Check for Unauthorised access (forced entry) Basement Check for leaks to oil tank Exposed woodwork Inspect exposed woodwork and surfaces below for signs of woodworm infestation. Report any beetles or fresh wood dust (Frass) Roof and floor voids Check roof and floor voids, inspect for signs of vermin and remove. Avoid using poison where bats are roosting. Lath and plaster ceilings Inspect from mobile access platform Suspended Ceilings Inspect from mobile access platform Stairs Check handraits Fire doors Check slam action and closing Windows Check window limiters remain in place. Review for rot Generally Ventilate the building Building Services (All once operational, Unless stated) Heating system Service heating system and update the service schedule. Water Ensure that all exposed tanks, water pipes and heating pipes are protected against frost. (Immediate) Fire fighting equipment Service fire extinguishers Ladders/Fallarest Check for correct operation/fixings. (Immediate) Emergency Lighting Replace lamps in light fittings (including access) Emergency Lighting Test and service (Immediate) Key switch test ONLY Fire detection Test fire alarm system, including smoke and heat detectors. (Immediate) Prainage Rod the system (Immediate) Mechnical extracts Check for correct operation/fixings. If Winng Check for correct operation/fixings. Lift Test and service Check for correct operation/fixings.	Inspect roof voids and internal spaces, particularly below parapet gutters and alongside downpipes. Report on any evidence of roof or gutter leaks. Check for Unauthorised access (forced entry) Basement Check for leaks to oil tank Exposed woodwork Inspect exposed woodwork and surfaces below for signs of woodworm infestation. Report any beetles or fresh wood dust (Frass) Roof and floor voids Check roof and floor voids, inspect for signs of vermin and remove. Avoid using poison where bats are roosting. Lath and plaster ceilings Inspect from mobile access platform Statif Contractor Statif Statirs Check handralis Check handralis Check sam action and closing Windows Check window limiters remain in place. Review for rot Generally Ventilate the building Building Services (All once operational, Unless stated) Bearing system Service heating system and update the service engineer Ensure that all exposed tanks, water pipes and heating pipes are protected against frost. (Immediate) Fire flighting equipment Service for correct operation/lixings. (Immediate) Fire detection Test and service (Immediate) Check for correct operation/lixings. (Contractor Trained Staff) Trai	Internal spaces generally below paraget gutters and alongside downpipes. Report on any evidence of roof or gutter leaks. Check for Unauthorised access (forced entry) Check for Unauthorised access platform Check for Inauthorised access platform Check for Inauthorised access platform Check for Contractor Check for Contractor Check fand allow voids. Inspect for signs of vermin and remove. Avoid using poison where bats are roosting. Check handralis Check handralis Check shan action and closing Check shand entry Check shand entry Check window limiters remain in place. Review for Trained Staff' Contractor Check shand entry Check window limiters remain in place. Review for Trained Staff' Check shand entry Contractor Check shand entry Check window limiters remain in place. Review for Trained Staff' Contractor Check shand entry Contractor Check shand entry Contractor Check for correct operation/fixings. (Immediate) Check for correct operation/fixings. (Immediate) Check for correct operation/fixings. (Immediate) Check for correct operation/fixings. Contractor Con	Inspect roof voids and internal spaces, particularly below parapet guitres and alongside downingbes. Personal of the voids and songside downingbes. Check for Insuthonised access (forced entry) Basement Check for Insuthonised access (forced entry) Check for Insuthonised access (forced entry) Exposed woodwork Inspect exposed woodwork and surfaces below for signs of woodwork indisstation. Report any before or fresh wood dust (firess) Foof and floor voids Check for find foor voids, inspect for signs of vormin and remove. Avoid using potent where the state are rootedly. Lath and plaster ceilings Inspect from mobile access platform Contractor Statif Contractor Cont	Inspect roof voids and internal spaces, particularly bidow parapid gutters and alongside downpipes. Placement Color of the bidow parapid gutters and alongside downpipes. Check for Unauthorised access forced entry! Placement Color of the bidow parapid gutters and alongside downpipes. Check for leaks to oil tank Check for deaks to oil tank Check for deaks to oil tank Check for death down oil tank Check for death down oil tank Check for death death for sight of the formation of the force oil for sight of the force oil for	Inspect roof-voide and internal seaces, pertously below paragret gurses and songside diswriptes. Perceiv paragret gurses and songside gurses are constituted gurses. Perceiv paragret gurses and songside gurses are constituted gurses are constituted gurses. Perceiv paragret gurses are constituted gurses are constituted gurses. Perceiv paragret gurses are constituted gurses are constituted gurses. Perceiv paragret gurses are constituted gurses are constituted gurses. Perceiv paragret gurses gurses gurses gurses gurses gurses. Perceiv paragret gurses gurses gurses gurses gurses gurses gurses. Perceiv paragret gurses gurses gurses gurses gurses gurses gurses gurses. Perceiv paragret gurses g	Thereal apaces generally improved that a company of the company of	## Auturnal security Programment Progra	release species generally interest interest spaces, particularly interest spaces generally interest generally generally interest generally interest generally generally interest generally genera	The control of the co	Deliveral governance Image: Control Cont	Personal part Personal Programs Persona	Accordance from the control of the c	Page of the Control	Part Contract Co	Processor (Control of Control o	Processor personal personal content Processor personal persona	Management Man

	Occasional and Regular Task	(S																		
Ref	Building Element	Maintenance Task	Responsibility	Frequency	Rate £/Hour	Time	Frequency	Annual Cost £	J	F	М	A	М	J	J	A	s	0	N	D
10	Sanitaryware and Fittings																			
10.1	Inspect sanitary fittings/ pipework and cisterns	Check overflows/ leaks. Check for damage	Trained Staff*	Bi monthly	£30.00	1.5	6	£270.00		✓		✓		✓		√		√		√
11	Specialist Fittings																			
11.1	Performance/ specialist lighting																			
		Check secured against falling	Specialist	Annually				£1,500.00			✓									
		Check operation	Specialist	Annually				£400.00			√									
11.2	Scenery lifting	Check for corrosion	Specialist	Annually				£1,000.00			✓									
12	Shared Areas																			
12.1	Steps	Re-fix loose treads	Contractor	Annually				£150.00					✓							
12.2	External lighting / Emergency Lighting	Inspect and repair missing lamps	Contractor	Annually				£400.00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
12.3	External Areas' maintenance	Weeding around building, particularly to Market Street	Contractor	4 hours per week in growing Season	£30.00		20.00	£0.00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	√
				Estimated Annual Total				£51,167.50												

RYDE TOWN HALL: 10 YEAR MAINTENANCE PLAN

	Cyclical tasks					Main project										
Ref	Building Element	Maintenance Task	Responsibility	Frequency	Budget Cost £	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2034
2.1	Decoration															
2.1.1	Rainwater Goods (South and West)	Repaint (includes scaffolding estimate)	Contractor	7 years	£5,000.00								√			
	Rainwater Goods (North and East elevations)	Repaint (includes scaffolding estimate)	Contractor	10 years (more sheltered)	£8,000.00											√
	Joinery (South and West elevations)	Repaint (includes scaffolding estimate)	Contractor	7 years	£120,000.00								√			
	Joinery (North and East elevations)	Repaint (includes scaffolding estimate)	Contractor	10 years (more	£110,000.00											√
	External metalwork with access in	(Repaint railings etc)	Contractor	sheltered) 7 years	£4,000.00								√			
	above (S&W) External metalwork with access in	(- 1, - 1	Contractor	10 years (more	£6,000.00								,			√
	above (N&E) Render (main walls) (S&W)	Fully scaffolded, redecoration.	Contractor	sheltered) 7 years	£25,000.00								√			
	Render (main walls) (E&N)	Fully scaffolded, redecoration.	Contractor	10 years (more	£25,000.00								•			./
	Clock Tower	·		sheltered)									1			Y
	Clock lower	Fully scaffolded, redecoration.	Contractor	7 years	£100,000.00								√			
0.0																
2.2	External walls															
2.2.1	External joinery/ metalwork	Joinery repairs	Contractor	With scaffold in place	10,000.00								✓			✓
0.00	Deleterate	Davis dia sus sustante del 1	Contract	With scaffold in	040,000,00											
2.2.2	Brickwork/ stonework repairs	Periodic on going repointing	Contractor	place	£18,000.00								√			1
2.4																
2.4.1	Building Services															
2.4.1			Electrical contractor registered with													
	Wiring and electrical installations	Inspect all wiring and electrical installations, including all portable electrical equipment, in	National Inspection Council for Electrical	5 years	£5,000.00						./					./
	Willing and electrical installations	accordance with current IEE regulations.	Installation Contracting or Electrical	5 years	25,000.00						•					V
			Contractors Association													
2.4.2	Security Alarm system	Inspect and test	Security system	Annual	£2,500.00		√	✓	√	√						
2.4.3	Lift Servicing	Inspect and test	contractor Specialist contractor	Annual	£1,500.00		√									
2.4.4	3		Electrical contractor		,			,	,	,	,	•	,	,		
		Inspect and service all heating installations,	registered with National Inspection													
	Hot Water and Heating system (assumes Gas)	including all portable electrical equipment, in accordance with regulations.	Council for Electrical Installation Contracting	Annual	£3,000.00		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
		accordance with regulations.	or Electrical Contractors													
2.4.5	Lightning Conductor	Inspect and test	Association Specialist contractor	10 years	£1,800.00											J
2.4.6	Chlorifiers check for legionella	Inspect and test	Specialist contractor	Annual	£3,000.00		√	√	✓	√	√	✓	✓	✓	✓	√
2.4.7	Fire Alarms	Inspect and test (selected zones sample points)	Specialist contractor	Annual	£1,000.00		✓	√	✓	✓	√	✓	✓	✓	✓	√
2.4.8	Emergency Lighting	Inspect and test ('3 hour drain' annual)	Specialist contractor	Annual	£1,000.00		✓	√	√	√	√	✓	√	✓	√	√
2.4.9	Air conditioning units	Inspect and test (Changing filters)	Specialist contractor	Annual	£3,000.00		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2.4.10			Electrical contractor registered with													
			National Inspection Council for Electrical		04.000.00					_						
	Periodic Replacement of fittings	On going replacements of lights, etc	Installation Contracting or Electrical	4 Times a year	£1,000.00		✓			√			√			✓
			Contractors Association													
2.4.11	Fire Extinguishers	(Test and replace)	Specialist contractor	Annual	£2,000.00		✓	√	✓	✓	√	✓	√	✓	✓	√
2.5	Other Items															
21	Review building replacement value for insurance purposes	To ensure correct rebuild value is used.	Specialist	5 years	£2,500.00					√					√	
	Tor insurance purposes															
2.6	Estimated Total Cost Per Year for	Cyclical tasks (Ex VAT)					£18,000	£17,850	£18,700	£29,325	£20,400	£21,250	£353,600	£22,950	£27,300	£292,610
		- ,					_,,550	,,,,,,,	_ ,. 33	,,,,,,	_,.55	,	2,550	,,,,,,	,,,,,,,	
2.7		ular and Occasional Tasks (increased at 5%					Ç51 160	£52 706	\$56 A10	£50 000	£62 104	£65 304	£68,569	£71 000	£75 500	£70 270
۷.1	per year for inflation)						201,108	200,120	200,412	೭೮೪,೭೮೮	202,194	200,304	200,009	211,998	£10,098	213,318
	Totals (Ex VAT)						£69,168	£71,576	£75,112	£88,558	£82,594	£86,554	£422,169	£94,948	£102,898	£371,988
	BUDGET estimates only, given in	good faith and without prejudice														

Ryde Town Hall: Conservation Management Plan: 6
The Goddard Partnership Limited 6
March 2024

FORT PURBROOK- MAINTENANCE PLAN

Notes

The Maintenance Programme has been developed in accordance with the guidance provided by Historic England: *Grants For Historic Buildings Monuments and Designed Landscapes: Maintenance Plans (2015).*

Costs have been provided **for guidance only**, and are based on 2024 prices. All figures exclude VAT. These are shown as increasing year on year by 5%, although recent increases in inflation have been significantly higher.

Where cost have been shown for regular tasks undertaken by a contractor, these are to be grouped to allow for a series of inspection tasks and repairs to be undertaken concurrently resulting in an economy of scale. If tasks are separated then the costs will be higher. In the regular task section, the costs are for inspect only and not necessarily for completing work.

Nominal sums are shown for items such as the glazing repair as these may not be needed annually, although the sums shown should be allowed to accumulate to cover future repair works. Additional items such as risk assessments are also needed but are not shown on the Plan, which focusses on principal building Items.

It is assumed that the main conservation works have been completed and the building is generally in a good condition with only regular maintenance now being needed. The date for achieving this position is shown as 2025.

Volunteers

Deemed to be competent persons with the skills appropriate for the task, but with direction by Trust staff. No charge will be made for their time. It should be aware that the Ryde Town Hall Trust (RTHT) remains liable for the actions of volunteers, and risk assessments should be prepared for their work. If the work is considered high risk or the appropriate skills are not available then a specialist contractor should be appointed.

Trained Staff

Deemed to be competent persons employed by Ryde Town Hall Trust with the skills appropriate for the task. Their hourly rate is nominally shown at £30/ hour. The Ryde Town Hall Trust (RTHT) remain liable for the actions of all staff and risk assessments should be prepared for their work. If the work is considered high risk or the appropriate skills are not available then a specialist contractor should be appointed.

Consultants

Deemed to be competent persons employed by Ryde Town Hall Trust with the skills appropriate for the task. Their costs should be quoted for in advance, or potentially on the basis of a retainer/hourly rate. The consultants will be expected to have their own public liability and professional indemnity insurances. The consultants will need to demonstrate that they possess the required specialist training (ie use of cherry picker, crack monitoring etc).

Contractors

Companies, individuals or firms experienced in the tasks described. Covered by their own liability insurance. All will make a charge for their services. Works may be tendered.

The Goddard Partnership Limited

The Old Fire Station
Upper Basingwell Street
Bishops Waltham
SO32 1PF

March 2024